



ATTACHMENT 4 DRAWINGS

PROPOSED ASPHALT REPAIR AT EMBASSY COMPOUND


Area-1: Front parking lot




Area-2: Near the red container



Area-3: Near the motor pool



Area-4: Front of warehouse



Area-5: Behind the warehouse

